

SASHIBALA SAHA F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800101

Distance in Kms. a) From Block H.Q. 2
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/1

Class: I -- IV

Students: 229

Teachers: 5

Pupil Teacher Ratio: 45.80

Total class rooms area: 700 Sq. ft.

Space per Student: 3.06 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 5 | 2 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 3 Need minor repair 2 Need maior repair 0

Whether Common toilet is present: No

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Well

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: Yes

KALNA AMBIKA MAHISMARDINI F.P

Circle Name: KALNA EAST

DISE Code: 3800102

Distance in Kms. a) From Block H.Q. 1
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/1

Class: I -- IV

Students: 366

Teachers: 8

Pupil Teacher Ratio: 45.75

Total class rooms area: 2800 Sq. ft.

Space per Student: 7.65 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 8 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 5 Need minor repair 0 Need maior repair 2

Whether Common toilet is present: No

Whether Girls toilet is present: No

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: Yes

DANGAPARA CHANDI CHARAN F.P.

Circle Name: KALNA EAST

DISE Code: 3800201

Distance in Kms. a) From Block H.Q. 0
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/2

Class: I -- IV

Students: 95

Teachers: 3

Pupil Teacher Ratio: 31.67

Total class rooms area: 671 Sq. ft.

Space per Student: 7.06 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 0 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 2 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 1

Whether Common toilet is present: No

Whether Girls toilet is present: No

Whether Electricity in the School: Yes

Water facility is available: None

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: No

HARIJAN F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800202

Distance in Kms. a) From Block H.Q. 3
b) From CLR 0

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/2

Class: I -- IV

Students: 84

Teachers: 2

Pupil Teacher Ratio: 42.00

Total class rooms area: 700 Sq. ft.

Space per Student: 8.33 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 4 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No Response

Boundary Wall: No boundary wall

Whether Playground is presernt: No

KALNA HINDU GIRLS' F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800203

Distance in Kms. a) From Block H.Q. 2
b) From CLR 0

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/2

Class: I -- IV

Students: 221

Teachers: 4

Pupil Teacher Ratio: 55.25

Total class rooms area: 1200 Sq. ft.

Space per Student: 5.43 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 5 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 4 Need minor repair 1 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: Yes

VETERAMOHAL F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800301

Distance in Kms. a) From Block H.Q. 2
b) From CLR 0

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/3

Class: I -- IV

Students: 143

Teachers: 4

Pupil Teacher Ratio: 35.75

Total class rooms area: 470 Sq. ft.

Space per Student: 3.29 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 3 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Handpump

Whethr Library facility is available: No

Whether RAMP is present: No Response

Boundary Wall: No boundary wall

Whether Playground is presernt: No

KALNA G.S. F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800401

Distance in Kms. a) From Block H.Q. 1
b) From CLR 1



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/4

Class: I -- IV

Students: 84

Teachers: 3

Pupil Teacher Ratio: 28.00

Total class rooms area: 1200 Sq. ft.

Space per Student: 14.29 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 2 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 4 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: No

KATIGANGA F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800501

Distance in Kms. a) From Block H.Q. 3
b) From CLR 1

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/5

Class: I -- IV

Students: 145

Teachers: 3

Pupil Teacher Ratio: 48.33

Total class rooms area: 844 Sq. ft.

Space per Student: 5.82 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 2 | 0 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 1 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: No

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No Response

Boundary Wall: No boundary wall

Whether Playground is presernt: No

MAHISMARDINI F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800502

Distance in Kms. a) From Block H.Q. 3
b) From CLR 1

Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/5

Class: I -- IV

Students: 67

Teachers: 3

Pupil Teacher Ratio: 22.33

Total class rooms area: 840 Sq. ft.

Space per Student: 12.54 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 0 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 4 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: No

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: No



SRI SRI NIGAMANANDA VIDYAMANDI

Circle Name: KALNA EAST

DISE Code: 3800601

Distance in Kms. a) From Block H.Q. 4
b) From CLR 0

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/6

Class: I -- IV

Students: 252

Teachers: 7

Pupil Teacher Ratio: 36.00

Total class rooms area: 176 Sq. ft.

Space per Student: 0.70 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 0 | 1 |
| Partially pucca | 6 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 1 Need minor repair 0 Need maior repair 5

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: No

SRI SRI BIJOY KRISHNA G.S. F.P

Circle Name: KALNA EAST

DISE Code: 3800602

Distance in Kms. a) From Block H.Q. 4
b) From CLR 1

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/6

Class: I -- IV

Students: 172

Teachers: 4

Pupil Teacher Ratio: 43.00

Total class rooms area: 1060 Sq. ft.

Space per Student: 6.16 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 3 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 2 Need minor repair 1 Need maior repair 0

Whether Common toilet is present: No

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: Others

Whether Playground is presernt: No

LALJEE MAHARAJ F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800603

Distance in Kms. a) From Block H.Q. 1
b) From CLR 1



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/6

Class: I -- IV

Students: 201

Teachers: 5

Pupil Teacher Ratio: 40.20

Total class rooms area: 1800 Sq. ft.

Space per Student: 8.96 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 1 | 0 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 1 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: No

BARUIPARA D.C. F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800604

Distance in Kms. a) From Block H.Q. 3
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/6

Class: I -- IV

Students: 288

Teachers: 6

Pupil Teacher Ratio: 48.00

Total class rooms area: 250 Sq. ft.

Space per Student: 0.87 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 3 | 0 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 3 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: No

JEWDHARA MACHURA KHATUN F.P. S

Circle Name: KALNA EAST

DISE Code: 3800701

Distance in Kms. a) From Block H.Q. 1
b) From CLR 2



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/7

Class: I -- IV

Students: 185

Teachers: 5

Pupil Teacher Ratio: 37.00

Total class rooms area: 1150 Sq. ft.

Space per Student: 6.22 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 3 | 1 |
| Partially pucca | 1 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 3 | Need minor repair | 1 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Handpump

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: No

JEWDHARA MILAN KENDRA F.P. SCH

Circle Name: KALNA EAST

DISE Code: 3800702

Distance in Kms. a) From Block H.Q. 3
b) From CLR 1



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/7

Class: I -- IV

Students: 124

Teachers: 3

Pupil Teacher Ratio: 41.33

Total class rooms area: 1100 Sq. ft.

Space per Student: 8.87 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: No

LALBAGAN G.S. F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800703

Distance in Kms. a) From Block H.Q. 1
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/7

Class: I -- IV

Students: 239

Teachers: 5

Pupil Teacher Ratio: 47.80

Total class rooms area: 387 Sq. ft.

Space per Student: 1.62 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 6 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 3 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: No

JOGI PARA G.S. F.P. SCHOOL(NEW)

Circle Name: KALNA EAST

DISE Code: 3800901

Distance in Kms. a) From Block H.Q. 1
b) From CLR 0

Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/9

Class: I -- IV

Students: 45

Teachers: 2

Pupil Teacher Ratio: 22.50

Total class rooms area: 388 Sq. ft.

Space per Student: 8.62 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 2 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 0 | Need minor repair | 2 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: No Response

Whether Playground is presernt: No



JOGI PARA G.S. F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3800902

Distance in Kms. a) From Block H.Q. 0
b) From CLR 0

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/9

Class: I -- IV

Students: 47

Teachers: 2

Pupil Teacher Ratio: 23.50

Total class rooms area: 650 Sq. ft.

Space per Student: 13.83 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: No

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Handpump

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: No Response

Whether Playground is presernt: No

RAMKRISHNA F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801001

Distance in Kms. a) From Block H.Q. 1
b) From CLR 1



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/10

Class: I -- IV

Students: 189

Teachers: 5

Pupil Teacher Ratio: 37.80

Total class rooms area: 800 Sq. ft.

Space per Student: 4.23 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 4 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: No

ST. MARYS F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801002

Distance in Kms. a) From Block H.Q. 3
b) From CLR 1



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/10

Class: I -- IV

Students: 293

Teachers: 7

Pupil Teacher Ratio: 41.86

Total class rooms area: 1798 Sq. ft.

Space per Student: 6.14 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 6 | 2 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 3 Need minor repair 2 Need maior repair 1

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Handpump

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: No

KALNA JAPAT G.S. F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801003

Distance in Kms. a) From Block H.Q. 3
b) From CLR 0

Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/10

Class: I -- IV

Students: 37

Teachers: 2

Pupil Teacher Ratio: 18.50

Total class rooms area: 657 Sq. ft.

Space per Student: 17.76 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 1 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 1 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: No



KALNA F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801101

Distance in Kms. a) From Block H.Q. 1
b) From CLR 0

Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/11

Class: I -- IV

Students: 255

Teachers: 6

Pupil Teacher Ratio: 42.50

Total class rooms area: 896 Sq. ft.

Space per Student: 3.51 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 6 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: Pucca but broken

Whether Playground is presernt: Yes



MADHUBAN F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801201

Distance in Kms. a) From Block H.Q. 2
b) From CLR 0

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/12

Class: I -- IV

Students: 155

Teachers: 4

Pupil Teacher Ratio: 38.75

Total class rooms area: 1080 Sq. ft.

Space per Student: 6.97 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 1 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: Pucca but broken

Whether Playground is presernt: No

BARAMITRA PARA G.S. F.P. SCHOO

Circle Name: KALNA EAST

DISE Code: 3801202

Distance in Kms. a) From Block H.Q. 3
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/12

Class: I -- IV

Students: 105

Teachers: 4

Pupil Teacher Ratio: 26.25

Total class rooms area: 765 Sq. ft.

Space per Student: 7.29 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 4 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: No

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: Pucca

Whether Playground is presernt: Yes

NEW MADHUBAN F.P.SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801204

Distance in Kms. a) From Block H.Q. 2
b) From CLR 1

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/12

Class: I -- IV

Students: 107

Teachers: 2

Pupil Teacher Ratio: 53.50

Total class rooms area: 1080 Sq. ft.

Space per Student: 10.09 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 2 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: No

Whether Girls toilet is present: No

Whether Electricity in the School: No

Water facility is available: Handpump

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: No

JAGANNATH KAIRY F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801301

Distance in Kms. a) From Block H.Q. 2
b) From CLR 2

Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/13

Class: I -- IV

Students: 130

Teachers: 3

Pupil Teacher Ratio: 43.33

Total class rooms area: 1156 Sq. ft.

Space per Student: 8.89 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 3 | 1 |
| Partially pucca | 1 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 3 | Need minor repair | 0 | Need maior repair | 1 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: No

Water facility is available: Others

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: No Response

Whether Playground is presernt: No

SRI SRI JAGANNATH JEU F.P. SCH

Circle Name: KALNA EAST

DISE Code: 3801401

Distance in Kms. a) From Block H.Q. 1
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/14

Class: I -- IV

Students: 85

Teachers: 3

Pupil Teacher Ratio: 28.33

Total class rooms area: 369 Sq. ft.

Space per Student: 4.34 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 2 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: No Response

Whether Electricity in the School: No Response

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: No

JANANESWAR JIW F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801402

Distance in Kms. a) From Block H.Q. 1
b) From CLR 1

Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/14

Class: I -- IV

Students: 112

Teachers: 3

Pupil Teacher Ratio: 37.33

Total class rooms area: 1440 Sq. ft.

Space per Student: 12.86 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 2 | 0 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 0 | Need minor repair | 0 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: Yes

Whether Electricity in the School: Yes

Water facility is available: Handpump

Whethr Library facility is available: No

Whether RAMP is present: Yes

Boundary Wall: Pucca

Whether Playground is presernt: No

SHYAMGANJ G.S. F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801501

Distance in Kms. a) From Block H.Q. 1
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/15

Class: I -- IV

Students: 151

Teachers: 4

Pupil Teacher Ratio: 37.75

Total class rooms area: 1213 Sq. ft.

Space per Student: 8.03 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: No Response

Whether Playground is presernt: Yes

SUBARNANAGAR G.S. F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801502

Distance in Kms. a) From Block H.Q. 3
b) From CLR 2

Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO.15

Class: I -- IV

Students: 329

Teachers: 10

Pupil Teacher Ratio: 32.90

Total class rooms area: 1560 Sq. ft.

Space per Student: 4.74 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 9 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 4 Need minor repair 3 Need maior repair 2

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No Response

Boundary Wall: Pucca

Whether Playground is presernt: No

GHOSH PARA G.S. F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801601

Distance in Kms. a) From Block H.Q. 1
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/16

Class: I -- IV

Students: 56

Teachers: 2

Pupil Teacher Ratio: 28.00

Total class rooms area: 763 Sq. ft.

Space per Student: 13.63 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 2 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: Yes

Whether RAMP is present: No

Boundary Wall: No boundary wall

Whether Playground is presernt: Yes

GARORDANGA SEN'S F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801701

Distance in Kms. a) From Block H.Q. 0
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/17

Class: I -- IV

Students: 25

Teachers: 2

Pupil Teacher Ratio: 12.50

Total class rooms area: 200 Sq. ft.

Space per Student: 8.00 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 0 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 1

Whether Common toilet is present: No

Whether Girls toilet is present: No

Whether Electricity in the School: No

Water facility is available: None

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: No Response

Whether Playground is presernt: No

KALNA MAHARAJ F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801702

Distance in Kms. a) From Block H.Q. 3
b) From CLR 1



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/17

Class: I -- IV

Students: 187

Teachers: 5

Pupil Teacher Ratio: 37.40

Total class rooms area: 960 Sq. ft.

Space per Student: 5.13 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 4 | 0 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 0 | Need minor repair | 1 | Need maior repair | 0 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: Yes

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No Response

Boundary Wall: Pucca

Whether Playground is presernt: Yes

JANAKALYAN F.P. SCHOOL

Circle Name: KALNA EAST

DISE Code: 3801703

Distance in Kms. a) From Block H.Q. 0
b) From CLR 0



Medium of the School: Bengali

Gram Sansad / Ward Name: WORD NO/17

Class: I -- IV

Students: 44

Teachers: 2

Pupil Teacher Ratio: 22.00

Total class rooms area: 288 Sq. ft.

Space per Student: 6.55 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 0 | 0 |
| Partially pucca | 3 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

| | | | | | |
|------|---|-------------------|---|-------------------|---|
| Good | 0 | Need minor repair | 0 | Need maior repair | 3 |
|------|---|-------------------|---|-------------------|---|

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: No

Water facility is available: None

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: Hedges

Whether Playground is presernt: No

SRI SRI SHYAM SUNDAR VIDYAPETH

Circle Name: KALNA EAST

DISE Code: 3801801

Distance in Kms. a) From Block H.Q. 1
b) From CLR 0

Medium of the School: Bengali



Gram Sansad / Ward Name: WORD NO/18

Class: I -- IV

Students: 128

Teachers: 4

Pupil Teacher Ratio: 32.00

Total class rooms area: 200 Sq. ft.

Space per Student: 1.56 Sq. ft.

Status of School Building: Government

Type of Classrooms and other rooms:

| Type | Classrooms | Other rooms |
|-----------------|------------|-------------|
| Pucca | 1 | 1 |
| Partially pucca | 0 | 0 |
| Kuccha | 0 | 0 |

Condition of classrooms:

Good 0 Need minor repair 0 Need maior repair 0

Whether Common toilet is present: Yes

Whether Girls toilet is present: No

Whether Electricity in the School: No

Water facility is available: Tap Water

Whethr Library facility is available: No

Whether RAMP is present: No

Boundary Wall: Pucca but broken

Whether Playground is presernt: No